

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20161007-E487117  
**Report Reference** E487117-20161006  
**Issue Date** 2016-OCTOBER-07

**Issued to:** San Antonio Armature Works  
1015 North Colorado St.  
San Antonio TX 78207

**This is to certify that  
representative samples of**

MOTORS AND GENERATORS, REBUILT FOR USE IN  
HAZARDOUS LOCATIONS  
General Coverage

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** UL 674, Electric Motors and Generators for Use in  
Hazardous (Classified) Locations

**Additional Information:** See the UL Online Certifications Directory at  
[www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's  
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please  
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

